

REPLACEMENT LABELS

MEMORY CONSOLE

WARNING:
TURN POWER OFF BEFORE PLUGGING
IN ANY EXPANSION MODULE!

DO NOT connect any Expansion Module to this unit until you **TURN OFF** the **POWER SWITCH** on the back of the **SmartWriter™ PRINTER MODULE . . .** or remove the plug from the wall outlet.

Printed in U.S.A. 41793

IMPORTANT NOTICE

1. Data Packs should be stored away from **ALL** Electrical Appliances when not in use. In particular, **DO NOT** store Data Packs on TV set, Memory Console, or **ADAM PRINTER**.
 2. **DO NOT TURN POWER ON OR OFF** with Data Pack in Unit.
- NOTE: Failure to observe these precautions may cause Data Pack Damage.

Printed in U.S.A.

ADAM™

Coleco Industries, Inc., Amsterdam, NY 12010

Serial #

Model #

F.C.C. ID#

COLECO INDUSTRIES, INC.

For service help call:
1 +800+842-1225
(Nationwide)

PRINTED IN U.S.A. 41867

This device complies with FCC Rule Part 15. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference that may be received, including interference that may cause undesired operation.

DATA DRIVES

WARNING: TURN POWER OFF BEFORE PLUGGING
IN A DATA DRIVE!

DO NOT connect the Data Drive to or remove it from **ADAM™** until you **TURN OFF** the **POWER SWITCH** on the back of the **SmartWriter™ PRINTER MODULE** or remove the plug from the wall outlet.

Printed in U.S.A. 42043

WARNING: TURN POWER OFF BEFORE PLUGGING
IN A DATA DRIVE!

DO NOT connect the Data Drive to or remove it from **ADAM™** until you **TURN OFF** the **POWER SWITCH** on the back of the **SmartWriter™ PRINTER MODULE** or remove the plug from the wall outlet.

Printed in U.S.A. 42043

AUTODIALER

ADAM™ AUTODIALER

SERIAL # _____ MODEL # 7815

FCC ID # **BNV8437815** RINGER EQUIV. 0.0B

FCC REG. # _____

Coleco Industries, Inc., Amsterdam, NY 12010

Certified to comply with the limits for a Class B computing device pursuant to Subpart J of Part 15 of FCC Rules. See instructions if interference to radio reception is suspected. Complies with Part 68, FCC Rules.

Printed in U.S.A. 42722A

NOTICE

**BE SURE TO UNPLUG ADAM™ LINE CORD
BEFORE INSERTING THIS DEVICE**

Printed in U.S.A.
300111

KEYBOARD/PRINTER

ADAM™

Coleco Industries, Inc., Amsterdam, NY 12010

Serial #

Model #

F.C.C. ID#

COLECO INDUSTRIES, INC.

For service help call:
1 +800+842-1225
(Nationwide)

PRINTED IN U.S.A. 41867

This device complies with FCC Rule Part 15. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference that may be received, including interference that may cause undesired operation.

ADAM™

Coleco Industries, Inc., Amsterdam, NY 12010

Serial #

Model #

F.C.C. ID#

COLECO INDUSTRIES, INC.

For service help call:
1 +800+842-1225
(Nationwide)

PRINTED IN U.S.A. 41867

This device complies with FCC Rule Part 15. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference that may be received, including interference that may cause undesired operation.

DISK DRIVE

ADAM™ 5¼" DISK DRIVE

Serial # 501C-700-

Model #7817

F.C.C. ID: #BNV6PD7817
COLECO INDUSTRIES, INC.
Made in Singapore

For service help call:
1 +800+842-1225
(Nationwide)

42773A

Certified to comply with the limits for a Class B computing device pursuant to Subpart J of Part 15 of FCC Rules. See instructions if interference to radio reception is suspected.

WARNING

DO NOT BLOCK HEAT VENTS!

Stacking disk drives or otherwise covering heat vents may cause damage to disk drives or disks.

Printed in U.S.A. 30004

MODEM

MODEL # 7818

SERIAL

F.C.C. ID # BNV8N27818

No

COLECO INDUSTRIES, INC.
AMSTERDAM, NY 12010
Complies with Part 68, FCC Rules.
FCC registration number
E4V8N2-70317-DM-R.
Ringer Equiv. 0.0B

FOR SERVICE HELP CALL:
1-800-842-1225
(NATIONWIDE)

PRINTED IN USA

42750

Certified to comply with the limits for a Class B computing device pursuant to Subpart J of Part 15 of FCC Rules. See instructions if interference to radio reception is suspected.

NOTICE

**BE SURE TO UNPLUG ADAM™ LINE CORD
BEFORE INSERTING THIS DEVICE**

Printed in U.S.A.
300111